



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70515

Inspection Report

Project Name: 5232 Jade Circle ~ COBI	Date: 08/09/2016 Any pm
Address: 5232 Jade Circle ~ COBI, Belle Isle, Orange County, FL	Permit No: 2016-04-009
Client: City of Belle Isle	Lot No.:
ProjectNo.: 0115.1600266.0000-0115-01	Contact: Teresa Kiggans at 407-835-7880
Scope of Inspection: Final Mechanical Inspection	
Inspection Type: See Scope	

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/09/2016	No access for inspection...FBC 110.1, FBC 110.5	William Moody

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489