



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70342

Inspection Report

Project Name: 5452 Ming Drive ~ COBI

Date: 07/29/2016 Any am

Address: 5452 Ming Drive ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-06-064

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600287.0000-0115-03

Contact: Clayton Van Camp at 407-341-9382

Scope of Inspection: Final Electrical Inspection for Boat Dock

Inspection Type: **Electrical - Final**

Disposition of Inspection: **Pass**

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
07/29/2016	Electrical Final Inspection for Boat Dock	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466