



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70517

Inspection Report

Project Name: 5465 Chiswick Cir ~ COBI

Address: 5465 Chiswick Cir ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600376.0000-0115-01

Scope of Inspection: Final Mechanical Inspection

Inspection Type: See Scope

Date: 08/11/2016 Any any

Permit No: 2016-07-001

Lot No.:

Contact: Alan Thrift at 407-497-425

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/11/2016	FBC R 110.1 Access required	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362