



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70458

Inspection Report

Project Name: 5820 Cove Drive ~ COBI

Date: 08/02/2016 Any pm

Address: 5820 Cove Drive ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-07-032

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600014.0000-0115-02

Contact: Melissa Anderson at 407-291-1644

Scope of Inspection: Final Mechanical Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489