



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70784

## Inspection Report

Project Name: 6101 S. Orange Avenue ~ COBI	Date: 08/11/2016 Any am
Address: 6101 S. Orange Avenue ~ COBI, Belle Isle, Orange County, FL	Permit No: 2016-08-010
Client: City of Belle Isle	Lot No.:
ProjectNo.: 0115.1600434.0000-0115-01	Contact: Jorge Gauvin at 407-814-0244
Scope of Inspection: Rough Mechanical Inspection	
Inspection Type: See Scope	

Disposition of Inspection: Partial Pass

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/11/2016	Exhaust duct light test.	William Moody

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489