



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70852

## Inspection Report

Project Name: 6101 S. Orange Avenue ~ COBI commercial

Date: 08/16/2016 Any am

Address: 6101 S. Orange Avenue ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-08-010

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600434.0000-0115-01

Contact: George Gauvin at 407-814-0244

Scope of Inspection: Rough Mechanical Inspection

Inspection Type: Mechanical - Rough In

Disposition of Inspection: Pass

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/17/2016	Per Jim: 1st duct wrap.	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: James Pappalardo, BN5706