



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70936

Inspection Report

Project Name: 6101 S. Orange Avenue ~ COBI commercial

Date: 08/17/2016 Any am

Address: 6101 S. Orange Avenue ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-08-010

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600434.0000-0115-01

Contact: Jorge Gauvin at 407-814-0244

Scope of Inspection: Rough Mechanical Inspection

Inspection Type: See Scope

Disposition of Inspection: Partial Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/17/2016	2nd layer of Fire wrap on hood exhaust duct.	William Moody

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489