

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70513

Inspection Report

Project Name: 6501 Matchett Road ~ COBI

Address: 6501 Matchett Road ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600430.0000-0915-01

Date: 08/02/2016 Any any

Permit No: 2016-08-005

Lot No.:

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW app for mechanical permit one 2.5 ton change out no ductwork

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

Task DateTask NoteUser Name08/03/2016App approved by plans examiner Art Barthlow.Susan Manchester

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Susan Manchester