3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71004

## **Inspection Report**

Project Name: 6501 Matchett Road ~ COBI			Date:	08/17/2016 Any any
Address:	s: 6501 Matchett Road ~ COBI, Belle Isle, Orange County, FL			2016-08-005
Client: City of Belle Isle			Lot No.:	
ProjectNo.: 0115.1600430.0000-0115-01		Contact:	Joseph Springer at 407-607-1308	
Scope of Inspection:		Final Mechanical Inspection		
Inspection Type:		See Scope		
Disposition of Inspection: Pass				

## Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489

W. Z.D. Moody