



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71613

Inspection Report

Project Name: 6806 Seminole Avenue ~ COBI

Date: 08/30/2016 Any any

Address: 6806 Seminole Avenue ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-12-016

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400171.0000-0115-01

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: Drive by this address and see if the Demo has ben done on the mobile home pad. Weather permitting take a photo.

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

| <u>Task Date</u> | <u>Task Note</u> | <u>User Name</u> |
|------------------|--|------------------|
| 08/30/2016 | Lot cleared, no signs of Demo work done. | Luis Colon |

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362