



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70752

Inspection Report

Project Name: 6838 Seminole Drive ~ COBI
Address: 6838 Seminole Drive ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1600389.0000-0915-01

Date: 08/11/2016 Any any
Permit No: 2016-07-019
Lot No.:
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW roof app for boat dock

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/12/2016	Passed via email per Art Barthlow	Susan Manchester

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Susan Manchester