



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70381

Inspection Report

Project Name: 7145 Lake Drive ~ COBI

Date: 07/29/2016 Any am

Address: 7145 Lake Drive ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-04-005

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501547.0000-0115-04

Contact: Jaime Bojanowski at 407-733-2067

Scope of Inspection: Final Roof Inspection for pavilion

Inspection Type: Roofing - Final

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
07/29/2016	Final Roof Inspection for Pavilion	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466