



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70805

Inspection Report

Project Name: 7425 Lake Drive- COBI

Date: 08/12/2016 Any am

Address: 7425 Lake Drive, Belle Isle, Orange County, FL

Permit No: 2016-02-035

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300595.0000-0115-08

Contact: Indira Gonzalez-Rosas at 407-809-5311

Scope of Inspection: Final Building Inspection for Door

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/12/2016	Final Building Inspection for Door	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466