



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70627

Inspection Report

Project Name: 7902 Daetwyler Drive ~ COBI
Address: 7902 Daetwyler Drive ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400010.0000-0115-06

Date: 08/08/2016 Any any
Permit No: 2016-12-033
Lot No.:
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW revision to bldg permit - move bathrooms and change windows to casement windows

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927