



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71318

Inspection Report

Project Name: 7902 Daetwyler Drive ~ COBI

Date: 08/24/2016 Any am

Address: 7902 Daetwyler Drive ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-12-033

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400010.0000-0115-06

Contact: Keith Hastings at 407-468-8294

Scope of Inspection: Lintel Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/24/2016	Lintel Inspection	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466