



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70791

Inspection Report

Project Name:	Belle Vista HOA Lot for Gate to Community	Date:	08/10/2016 Any any
Address:	Belle Vista HOA Lot for Gate to Communit, Belle Isle, Orange County, FL	Permit No:	2016-08-013
Client:	City of Belle Isle	Lot No.:	
ProjectNo.:	0115.1600438.0000-0115-01	Contact:	Susan Manchester at 407 581 8161
Scope of Inspection:	REVIEW low voltage app for cameras, access controls and barrier arms to be added to existing HOA entrance gate.		
Inspection Type:	See Scope		

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927