



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71500

Inspection Report

Project Name: Belle Vista on Lake Conway HOA Entrance Gate - COBI

Date: 08/26/2016 Any any

Address: Belle Vista HOA Lot for Gate to Communit, Belle Isle, Orange County, FL

Permit No: 2016-08-038

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600438.0000-0115-02

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW electrical app for gates & outlet

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927