



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88468

Inspection Report

Project Name: 1406 Swann Ave - COBI

Address: 1406 Swan Ave, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1300572.0000-0115-08

Scope of Inspection: Final Building Inspection for Shed

Inspection Type: **See Scope**

Date: 08/22/2017 Any any

Permit No: 2017-07-081

Lot No.:

Contact: Laurie Green at 407-282-2444

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489