



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 85720

Inspection Report

Project Name: City of Belle Isle- Building Department Services COBI

Date: 08/24/2017 Any any

Address: 1600 Nela Avenue, Belle Isle, Orange County, FL 32809

Permit No:

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1000014.0000-0115-07

Contact: Dale Baker at Email

Scope of Inspection: Building Official Services

Inspection Type: **See Scope**

Disposition of Inspection: Complete

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927