3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 87325

Inspection Report

Project Name: 1624 Swann Avenue ~ COBI Date: 08/16/2017 Any any Address: 1624 Swann Avenue ~ COBI, Belle Isle, Orange County, FL Permit No: 2017-08-031 Client: Lot No .: City of Belle Isle ProjectNo.: Contact: 0115.1700302.0000-0115-01 Becky Romanovsky at 407.857.0889

Scope of Inspection: Final Mechanical Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489

W. Z. Moody