



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88262

## Inspection Report

Project Name: 1700 Idaho Ave - COBI  
Address: 1700 Idaho Ave - COBI, Belle Isle, Orange County, FL 32812  
Client: City of Belle Isle  
ProjectNo.: 0115.1300377.0000-0115-02

Date: 08/18/2017 Any any  
Permit No: 2017-08-107  
Lot No.:  
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW electrical permit app to replace existing overhead residential electrical service 125A same to same

Inspection Type: See Scope

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927