



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88666

Inspection Report

Project Name: 1701 Fulmer Road ~ COBI

Address: 1701 Fulmer Road ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1700210.0000-0115-01

Scope of Inspection: Final Building Inspection for Door Installation

Inspection Type: See Scope

Date: 08/24/2017 Any any

Permit No: 2017-05-084

Lot No.:

Contact: Rogelia Powell at 407-937-2840

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/24/2017	Fail / Post Permit on site / Provide access for inspection / FBC 110	William Moody

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489