



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88850

Inspection Report

Project Name: 1742 Wind Willow Road ~ COBI

Date: 08/25/2017 Any pm

Address: 1742 Wind Willow Road ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2017-08-119

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700326.0000-0115-01

Contact: Melinda Pasciuta at 407-898-6960

Scope of Inspection: Final Plumbing Inspection for Water Heater

Inspection Type: **See Scope**

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498