



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86495

Inspection Report

Project Name: 1816 Stafford Drive ~ COBI
Address: 1816 Stafford Drive ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700248.0000-0115-02

Date: 08/03/2017 Any any
Permit No: 2017-07-002
Lot No.:
Contact: Tyler Baumgartner at (407)-383-3226

Scope of Inspection: Pool Steel Bonding Inspection

Inspection Type: **See Scope**

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489