



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86196

Inspection Report

Project Name: 1833 Wind Drift Road ~ COBI
Address: 1833 Wind Drift Road ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700237.0000-0115-01

Date: 08/01/2017 Any any
Permit No: 2017-06-082
Lot No.:
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: Pick up boat dock plans at UES office and deliver to COBI City Hall (1600 Nela Ave) for zoning review

Inspection Type: **See Scope**

Disposition of Inspection: Complete

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489