



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86470

## Inspection Report

Project Name: 2121 McCoy Road (ROYAL PALACE CONDOS) ~ COBI

Date: 08/02/2017 Any am

Address: 2121 McCoy Road (ROYAL PALACE CONDOS) ~ COBI,  
Belle Isle, Orange County, FL

Permit No: 2016-09-022

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600142.0000-0115-03

Contact: Massimo Napolitano at (407) 460  
3061

Scope of Inspection: Composite Deck Inspection

Inspection Type: See Scope

Disposition of Inspection: Partial Pass

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/02/2017	Section 2 and 3	William Moody

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489