



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86582

Inspection Report

Project Name: 2493 Trentwood Blvd ~ COBI

Address: 2493 Trentwood Blvd ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1700287.0000-0115-01

Date: 08/04/2017 Any am

Permit No: 2017-07-098

Lot No.:

Contact: Indira Gonzalez-Rosas at 407-809-5311

Scope of Inspection: Final Building Inspection for Window Installation

Inspection Type: See Scope

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489