



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 87281

Inspection Report

Project Name: 2502 Oak Island Pointe ~ COBI
Address: 2502 Oak Island Pointe ~ COBI, Belle Isle, Orange County,
FL
Client: City of Belle Isle
ProjectNo.: 0115.1700202.0000-0115-02
Scope of Inspection: Final Building Inspection for wall & columns
Inspection Type: See Scope

Date: 08/16/2017 Any any
Permit No: 2017-08-021
Lot No.:
Contact: Melissa McGee at 407-620-4633

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489