



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 89221

Inspection Report

Project Name: 2931 Cullen Lake Shore Drive ~ COBI
Address: 2931 Cullen Lake Shore Drive ~ COBI, Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700325.0000-0115-01
Scope of Inspection: Final Building Inspection for window
Inspection Type: **See Scope**

Date: 08/30/2017 Any any
Permit No: 2017-08-114
Lot No.:
Contact: Dave Hewitt at 407-701-0914

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489