



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 87326

Inspection Report

Project Name: 3616 Ponceau Street ~ COBI

Address: 3616 Ponceau Street ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1500830.0000-0115-05

Scope of Inspection: Roof In-Progress Inspection

Inspection Type: **See Scope**

Date: 08/16/2017 Any pm

Permit No: 2017-07-093

Lot No.:

Contact: Jessica Graf at (407) 851-0680

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489