3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 87014

## **Inspection Report**

Project Name: 3720 Saint Moritz Street ~ COBIDate: 08/10/2017 Any anyAddress: 3720 Saint Moritz Street ~ COBI, Belle Isle, Orange County, FLPermit No: 2017-08-060Client: City of Belle IsleLot No.:ProjectNo.: 0115.1700236.0000-0115-04Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW plumbing permit app to move drain

Inspection Type: See Scope

**Disposition of Inspection:** Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Jole Baker

Inspector: Dale Baker, BN 3927