



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 87280

Inspection Report

Project Name: 4118 Isle Vista Avenue ~ COBI

Date: 08/16/2017 Any any

Address: 4118 Isle Vista Avenue ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2017-06-013

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600228.0000-0115-13

Contact: Robyn Heinmiller at 407-656-1470

Scope of Inspection: Final Roof Inspection for boathouse

Inspection Type: **See Scope**

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489