



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88169

Inspection Report

Project Name: 4124 Isle Vista Avenue ~ COBI
Address: 4124 Isle Vista Avenue ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400381.0000-0115-17
Scope of Inspection: Final Roof Inspection for boat dock
Inspection Type: **See Scope**

Date: 08/18/2017 Any any
Permit No: 2017-08-002
Lot No.:
Contact: Katlynn Kellum at 407-821-9275

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489