



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86564

Inspection Report

Project Name: 4125 Arajo Court ~ COBI

Address: 4125 Arajo Court ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1700281.0000-0115-01

Scope of Inspection: Slab Inspection

Inspection Type: **See Scope**

Date: 08/03/2017 Any any

Permit No: 2017-07-077

Lot No.:

Contact: Bryan Dorion at 407-925-4987

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489