



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 87315

Inspection Report

Project Name: 4202 Belle Grove Court ~ COBI

Date: 08/17/2017 Any am

Address: 4202 Belle Grove Court ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2017-08-027

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700300.0000-0115-01

Contact: Jim Radosevich at 407-851-5954

Scope of Inspection: Final Mechanical Inspection for 4ton change-out

Inspection Type: **See Scope**

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489