

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 87021

Inspection Report			
Project Na	me: 4203 Kandra Court ~ COBI		
Address:	4203 Kandra Court ~ COBI, Belle Isle, Orange County, FL		

 Client:
 City of Belle Isle

 ProjectNo.:
 0115.1600560.0000-0115-02

 Scope of Inspection:
 Final Building Inspection for Windows & Doors

 Inspection Type:
 See Scope

Date		08/11/2017 Any any
Perm	it No:	2017-08-001
Lot No.:		
Conta	act:	Nicole Ford at 407-440-2874

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector:

William Moody, BN4489

W. Z. Moody