



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 87228

Inspection Report

Project Name: 4214 Belle Grove Court ~ COBI

Date: 08/15/2017 Any any

Address: 4214 Belle Grove Court ~ COBI, Belle Isle, Orange County,
FL 32812

Permit No: 2017-08-034

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700304.0000-0115-03

Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIEW electrical permit app for pool

Inspection Type: See Scope

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927