



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 85927

Inspection Report

Project Name: 4231 Playa Court ~ COBI
Address: 4231 Playa Court ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700239.0000-0115-01
Scope of Inspection: Roof In-Progress Inspection
Inspection Type: See Scope

Date: 07/31/2017 Any am
Permit No: 2017-06-099
Lot No.:
Contact: Cynthia Waters at 407-423-7570

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489