



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86929

Inspection Report

Project Name: 4322 Playa Court ~ COBI

Date: 08/11/2017 Any any

Address: 4322 Playa Court ~ COBI, Belle Isle, Orange County, FL

Permit No: 2017-07-033

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400358.0000-0115-02

Contact: Mrs. O'Brien at 407-267-3170

Scope of Inspection: Final Building Re-inspection for Garage Door

Inspection Type: **See Scope**

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489