



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 89112

Inspection Report

Project Name: 4400 Hoffner Ave O'Reilly's Auto ~ COBI commercial
 Address: 4400 Hoffner Ave O'Reilly's Auto ~ COBI, Belle Isle, Orange County, FL
 Client: City of Belle Isle
 ProjectNo.: 0115.1700161.0000-0115-01
 Scope of Inspection: Sheathing Inspection (roof)
 Inspection Type: See Scope

Date: 08/29/2017 Any any
 Permit No: 2017-04-061
 Lot No.:
 Contact: Pete Horning at 863 662 0899

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/29/2017	Metal roof attachment.	William Moody

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489