



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86375

## Inspection Report

Project Name: 4915 Gramont Avenue ~ COBI

Date: 08/04/2017 Any any

Address: 4915 Gramont Avenue ~ COBI, Belle Isle, Orange County,  
FL

Permit No: 2017-05-012

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700183.0000-0115-01

Contact: Tanya Higgins at 407-960-1604

Scope of Inspection: Final Mechanical Inspection

Inspection Type: **See Scope**

**Disposition of Inspection: Pass**

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489