



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88880

Inspection Report

Project Name: 5008 St. Marie Avenue - COBI

Address: 5008 St. Marie Avenue - COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1300580.0000-0115-01

Scope of Inspection: Final Roof Inspection

Inspection Type: **See Scope**

Date: 08/25/2017 Any any

Permit No: 2017-07-075

Lot No.:

Contact: Steve Gonzalez at (407) 470-7295

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489