



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86676

Inspection Report

Project Name: 5026 Saint Marie Avenue ~ COBI

Date: 08/07/2017 Any any

Address: 5026 Saint Marie Avenue ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2017-08-026

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501038.0000-0115-03

Contact: Collina Gast at 407-581-8161

Scope of Inspection: REVIEW electrical permit app for 4 photovoltaic panels

Inspection Type: **See Scope**

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927