



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88933

Inspection Report

Project Name: 5038 Oak Island Road ~ COBI
Address: 5038 Oak Island Road ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1600190.0000-0115-03

Date: 08/29/2017 Any any
Permit No: 2017-08-129
Lot No.:
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW building permit app for remodel - zoning approved

Inspection Type: **See Scope**

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927