



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86484

Inspection Report

Project Name: 5107 Gramont Avenue ~ COBI

Address: 5107 Gramont Avenue ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1500160.0000-0115-04

Scope of Inspection: Final Plumbing Inspection

Inspection Type: See Scope

Date: 08/03/2017 Any am

Permit No: 2017-05-046

Lot No.:

Contact: Craig Sweeney at 407-896-3136

Disposition of Inspection: Cancel

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/03/2017	Per John: contractor cancelled prior to arrival.	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: John Jackson, BN 906