



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88059

Inspection Report

Project Name: 5107 Gramont Avenue ~ COBI

Date: 08/17/2017 Any any

Address: 5107 Gramont Avenue ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2017-05-046

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500160.0000-0115-04

Contact: Russell Sweeney at 407-896-3136

Scope of Inspection: Final Plumbing Inspection to change-out 1 toilet, 1 sink & 1 shower in the master bathroom

Inspection Type: **See Scope**

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498