



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 89217

Inspection Report

Project Name: 5107 Gramont Avenue ~ COBI
Address: 5107 Gramont Avenue ~ COBI, Belle Isle, Orange County,
FL
Client: City of Belle Isle
ProjectNo.: 0115.1500160.0000-0115-05
Scope of Inspection: Final Plumbing Inspection for laundry room
Inspection Type: See Scope

Date: 08/30/2017 Any any
Permit No: 2017 -05-051
Lot No.:
Contact: John Ahern at 321-229-6803

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498