



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88784

Inspection Report

Project Name: 5121 Pleasure Island Road ~ COBI
Address: 5121 Pleasure Island Road ~ COBI, Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700322.0000-0115-01
Scope of Inspection: Roof In-Progress Inspection
Inspection Type: **See Scope**

Date: 08/24/2017 Any any
Permit No: 2017-08-106
Lot No.:
Contact: Johnny Simon at 4074302755

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489