



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 86925

Inspection Report

Project Name: 5130 Saint Michael Avenue ~ COBI

Date: 08/10/2017 Any any

Address: 5130 Saint Michael Avenue ~ COBI, Belle Isle, Orange
County, FL

Permit No: 2017-06-063

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700148.0000-0115-02

Contact: Iris Diaz at 407-578-6893

Scope of Inspection: Roof In-Progress Inspection

Inspection Type: **See Scope**

Disposition of Inspection: Pass

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489