



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 88472

Inspection Report

Project Name: 5206 St. Regis Place ~ COBI

Date: 08/22/2017 Any any

Address: 5206 St. Regis Place ~ COBI, Belle Isle, Orange County, FL 32809

Permit No: 2017-06-031

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500507.0000-0115-01

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: Red Tag (Issue Stop Work Order) for boat dock project per City manager Bob Francis. Dock not being built as approved.

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/22/2017	Dale Baker has taken care of this. Please contact Dale Baker for the status of this work order.	William Moody

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489